



Col C

03226.000110

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
JOHN HILBERT) Examiner: K. Feggins
Appl. No.: 10/673,044) Group Art Unit: 2861
Filed: September 26, 2003)
For: DIRECT THERMAL PRINTER)
U.S. Patent No.: 7,256,803 B2)
Issued: August 14, 2007) February 19, 2008

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

Certificate
FEB 22 2008
of Correction

**REQUEST FOR CERTIFICATE OF
CORRECTION UNDER RULE 323**

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

02/21/2008 M8ELE/E1 00000003 7256803

81 FC:1811

RECEIVED USPTO
Patent Publication

FEB 22 2008

Patentee's undersigned attorney may be reached in our Costa Mesa,
California office by telephone at (714) 540-8700.

All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Frank L. Cire
Attorney for Patentee
Registration No.: 42,419

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

FCHS_WS 1650262v1

RECEIVED-USPTO
Patent Publication

FEB 22 2008

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 7,256,803 B2

DATED : August 14, 2007

INVENTOR(S) : Hilbert

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 16, "having" should read -- has --;
Line 29, "0.3 mill-" should read -- 0.3 milli- --;
Line 39, "must." should read -- must --;
Line 46, "use" should read -- using --; and
Line 47, "sinks" should read -- sinks. --.

COLUMN 2:

Line 10, "lasers" should read -- laser --; and
Line 59, "discreet" should read -- discrete --.

COLUMN 3:

Line 10, "to head" should read -- to heat --.

COLUMN 5:

Line 6, "discreet" should read -- discrete --.

COLUMN 6:

Line 3, "be" should read -- by --.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,256,803 B2

RECEIVED-JSP-
PLANO: No. of add'l. copies
@ 30¢ per page

FEB 22 2008



Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,256,803 B2

DATED : August 14, 2007

INVENTOR(S) : Hilbert

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1:

Line 16, "having" should read -- has --;
Line 29, "0.3 mill-" should read -- 0.3 milli- --;
Line 39, "must." should read -- must --;
Line 46, "use" should read -- using --; and
Line 47, "sinks" should read -- sinks. --.

COLUMN 2:

Line 10, "lasers" should read -- laser --; and
Line 59, "discreet" should read -- discrete --.

COLUMN 3:

Line 10, "to head" should read -- to heat --.

COLUMN 5:

Line 6, "discreet" should read -- discrete --.

COLUMN 6:

Line 3, "be" should read -- by --.

RECEIVED-USPTO
Patent Publication

FEB 22 2008

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 7,256,803 B2

No. of add'l. copies
@ 30¢ per page

